



Vibracoustic CVAir Springs

RML 74287 C



● bolt or stud

○ hole

⊗ threaded hole

⊗ combinations stud

⊗ air inlet



RML 74287 C



Cross References

Goodyear	1R11-867
----------	----------





RML 74287 C



OEM Part Number	
Scania (Rear Axle)	2024287

